

CONVERSIÓN DE PULGADAS A MILÍMETROS

FRACCIÓN DE PULGADA	MILIMETROS	FRACCIÓN DE PULGADA	MILIMETROS	FRACCIÓN DE PULGADA	MILIMETROS	FRACCIÓN DE PULGADA	MILIMETROS
1/64	0,40	17/64	6,75	33/64	13,10	49/64	19,44
1/32	0,79	9/32	7,14	17/32	13,49	25/32	19,84
3/64	1,19	19/64	7,54	35/64	13,89	51/64	20,24
1/16	1,59	5/16	7,94	9/16	14,29	13/16	20,64
5/64	1,98	21/64	8,33	37/64	14,68	53/64	21,03
3/32	2,38	11/32	8,73	19/32	15,08	27/32	21,43
7/64	2,78	23/64	9,13	39/64	15,48	55/64	21,83
1/8	3,18	3/8	9,53	5/8	15,88	7/8	22,23
9/64	3,57	25/64	9,92	41/64	16,27	57/64	22,62
5/32	3,97	13/32	10,32	21/32	16,67	29/32	23,02
11/64	4,37	27/64	10,72	43/64	17,07	59/64	23,42
3/16	4,76	7/16	11,11	11/16	17,46	15/16	23,81
13/64	5,16	29/64	11,51	45/64	17,86	61/64	24,21
7/32	5,56	15/32	11,91	23/32	18,26	31/32	24,61
15/64	5,95	31/64	12,30	47/64	18,65	63/64	25,00
1/4	6,35	1/2	12,70	3/4	19,05	1	25,40

DIAMETRO EN PULGADAS	PASO EN HILOS POR PULGADA PARA CADA SISTEMA DE ROSCA										
	B.S.W.	B.S.F.	B.S.B.	B.S.C.	B.S.P.	B.S.P.T.	N.C.	N.F.	N.P.S.	N.P.T.	N.S.
1/16	60										60
5/64											64
3/32	48										48-50
7/64											48
1/8	40				28	28			27	27	40
9/64											40
5/32	32										32-36
3/16	24	32									24-32
7/32	24	28									24-32
1/4	20	26	26		19	19	20	28	18	18	27-27-32
5/16	18	22	26				18	24			20-27-32
3/8	16	20	26		19	19	16	24	18	18	20-27
7/16	14	18	26				14	20			24-27
1/2	12	16	26	18	14	14	13	20	14	14	12-24-27
9/16	12	16	26				12	18			27
5/8	11	14	26	18	14	14	11	18			46722
11/16	11	14									11-16
3/4	10	12	26	16	14	14	10	16	14	14	12-27
13/16	10	12									10
7/8	9	11	26	16	14	14	9	14			12-18-24
15/16	9										9
1	8	10	26	16	11	11	8	14	11,½	11,½	12-27

TABLA PARA ROSCAR

ROSCAS INGLESAS 55°		
B.S.W.	WHITWORTH	NORMAL
B.S.F.	"	FINA
B.S.B.	"	BRONCE
B.S.C.	"	CAÑOS DE LUZ
B.S.P.	"	GAS
B.S.P.T.	"	GAS CONICO

ROSCAS AMERICANAS 60°	
N.C.	NORMAL
N.F.	FINA
N.S.	PASOS ESPECIALES
N.P.S.	GAS
N.P.T.	GAS CONICO